



BMW Annual Report Details

Application Id: 25994696

| Particulars of the Occupier | |
|---|---|
| Annual report submit for year: | 2021 |
| Name of the authorized person: | Sonu Chhachia |
| Name of HCF or CBMWTF: | Eye Q Vision Pvt Ltd |
| Address for Correspondence: | Eye Q Vision Pvt Ltd, Ground Floor of Lasik Laser centre and Lasik Laser Lounge situated opp to Eye- |
| Address of Facility: | Ground Floor of Lasik Laser centre and Lasik Laser Lounge situated opp to Eye-Q Super Speciality Eye Hospitals, Ward No. 3, Tayal Garden, Barwala Road, Hisar |
| Tel. No.: | 8930069968 |
| Fax. No.: | 00 - 00 |
| E-mail ID: | abhishek.sharma@eyeqindia.com |
| URL of Website: | |
| GPS coordinates of HCF of CBMWTF: | |
| Ownership of HCF or CBMWTF: | Private |
| Status of Authorization under the BMW (Management and Handing) Rules: | |
| Authorization No.: | BMW21HIS12685748 |
| Valid Upto: | |
| Status of Consents under Water Act and Air Act.: | |
| Valid Upto: | |

| Health Care Facilities Details | |
|--|-------------------|
| HCF/CBMWTF Type: | HCF |
| No. of Beds(for Bedded Hospital): | 0 |
| Non-Bedded Hospital (Clinic or Blood Bank or Clinical Laboratory or Research Institute or Veterinary Hospital or any other): | Day care Hospital |
| Licence Number: | 185302741 |
| Licence date of expiry: | |

| Quantity of Waste Generated | |
|--|-----|
| Quantity of waste generated or disposed in Kg per annum (on monthly average basis) | |
| Yellow Category: | 122 |
| Red Category: | 12 |
| White Category: | 3 |
| Blue Category: | 2 |
| General Solid Waste: | 165 |

| Storage, Treatment, Transportation, Processing and Disposal Facility Details | |
|---|----------------------------------|
| Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum: | 0 |
| No of vehicles used for collection and transportation of BMW: | 2 |
| Name of the Common BMW Treatment Facility Operator through which wastes are disposed of: | Synergy waste Management Pvt Ltd |
| Details of the on-site storage facility: | |
| Size: | 10x4 |
| Capacity: | 10kg |
| Provision of on-site storage: | SAME |

| Disposal Facility | | | |
|-----------------------------|-----------------|------------------|--|
| Type of Treatment Equipment | Number of Units | Capacity(Kg/day) | Quantity Treated or Disposed(Kg/annum) |
| List is Empty | | | |

| Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum | | |
|---|--------------------|----------------|
| Type of waste | Quantity Generated | Where disposal |
| List is Empty | | |

| BMW Management Committee | |
|---------------------------------------|----|
| Do you have BMW management committee: | no |

| Training Conducted on BMW Details | |
|--|---|
| Number of training conducted on BMW Management: | 1 |
| Number of personnel trained: | 2 |
| Number of personnel trained at the time of induction: | 2 |
| Number of personnel not undergone any training so far: | 1 |
| Whether standard manual for training is available: | yes |
| Any other information: | We follow All The Intrusions Of Haryana Pollution Board |

| Details of the accident occurred | |
|---|---|
| No. of accident occurred: | 0 |
| Number of the persons affected: | 0 |
| Remedial Action taken: | 0 |
| Any Fatality occurred, details: | 0 |

| Other Details |
|----------------------|
|----------------------|

| | |
|---|---|
| Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?: | 0 |
| Details of Continuous online emission monitoring systems installed: | 0 |
| Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year: | 0 |
| It the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?: | 0 |
| Any other relevant information: | 0 |